## DEPARTMENT OF HEALTH SERVICES

107 SOUTH BROADWAY, ROOM 2011 LOS ANGELES, CA 90012

(213) 620-2380



SFUND RECORDS CTR 2090843

### PRELIMINARY ASSESSMENT SUMMARY

Western Electroplating Company 820 West Esther Street Long Beach, CA 90813 July 1985

Preparer: Richard Brausch Toxic Substances COntrol Division Southern California Section (213) 620-2380

#### History and Problem:

This site was first occupied in 1940 by an electric motor repair shop. There is no information available to indicate the name of the company or any other specific practices or processes.

In 1951, Western Electroplating Company began operating on this site. They operated a chrome electroplating facility, Wastes included neutralized acid solutions and clarifier sludges. These were regularly removed to a disposal site. The wastewater was regularly tested for disposal into the Los Angeles County industrial sewer. None of these tests showed the effluent over the standards. These processes continued through 1984.

In 1984, a fire destroyed the interior of the facility. In fighting the fire, the fire department spilled the acid and caustic solutions. These entered the sewer system, but were contained at a pumping station and later, legally disposed of. Since then, the site has been vacant, and the only equipment remaining is the three-stage clarifier, which is underground.

#### Recommendation:

No evidence of on-site disposal of hazardous wastes has been found in regulatory agency records. Though spillage of toxic materials occurred at the time of the fire, there is evidence that this situation was mitigated. Staff recommends no further action under the Abandoned Site Assessment program.

A copy of this P.A. will be provided to the City of Long Beach Department of Environmental Health.

# PRELIMINARY ASSESSMENT Region 9

. .

Preparer's 1	Name	Richard Brausch	Date	July 1985	
=		·			

		SOURCE	INFORMATION
1.	Site I.D. Number	RCRA	OAD 808 501 215
2.	Site Name	California Dept. of Health Services (DOHS) Abandoned Site Project (ASP), Solid Waste Information System (SWIS), Form 8015 01-05-82	Western Electroplating Company
3.	Site Location	DOHS, ASP, SWIS Form 8026, 01-05-82	820 West Esther Street Long Beach, CA 90813
4.	County	Same as #2	Los Angeles County
5.	Owner (Address & Telephone No.)	Los Angeles County Tax Assessor 07-08-85	Western Electroplating Company 1000 S. Petrolia Avenue Compton, CA 90221 (213) 639-9490
6.	Operator (Address & Telephone No.)	DOHS, Abandoned Site Assessment Program (ASAP) Industrial Waste	Western Electroplating Company 1000 S. Petrolia Avenue Compton, CA 90221 (213) 639-9490
7.	Type of Ownership	Same as #5	Private
8.	Status	DOHS, ASAP, Drive-by, Brausch/Wood, 05-31-85	Inactive
9.	Source Activity	a) Same as #6	1951-1984: Chrome Electroplating
		b) Long Beach City	1940-1951: Electric Motor Repair

Planning 03-01-85

# PRELIMINARY ASSESSMENT Region 9

Prepa	rer's Name Richard		Date July 1985
	continu	SOURCE	INFORMATION
10.	Years of Operation	a) Same as #8	1984 - present: vacant
	•	b) Same as #6	1951-1984: Western Electroplating Company
	·	c) Same as #9 (b)	1940-1951: Electric motor repair company
11.	Facility Type	a) Los Angeles County	1951-1984: sump, 3 stage clarifier
		b) Same as # 9 (b)	1940-1951: none documented
12.	Waste Type and Description	Same as #6	Western Electroplating: acid sludge, plating sludge and solution

#### 13. Contacts:

F. Banales, Senior Sanitarian, Long Beach Environmental Health (213) 427-7421

R.D. Deforest, production Manager, Western Electroplating (213) 639-9490

#### 14. Incidents:

05-25-84 Fire, responded to by Long Beach Fire Department, interior of

facility destroyed, all plating solutions spilled, later contained

and subsequently removed.

# 15. Inspections:

05-31-85: ASAP Drive-by, Brausch/Wood, Site currently vacant.

05-25-84: Long Beach Environmental Health, acid and caustic contamination

of site due to fire cleaned up shortly after.

03-22-83 ASP Drive-by, RP/SS, site active.

# 16. Enforcement History:

None documented.

## 17.a.Initial recommendation for further action:

No evidence of on-site disposal of hazardous wastes has been found in regulatory agency files. Though spillage of toxic materials occurred at the time of the fire, there is evidence that this situation was mitigated. Staff recommends no further action under the Abandoned Site Assessment Program.

A copy of this P.A. will be provided to the City of Long Beach Department of Environmental Health.

17.6. EPA recommends no further action. File documentation supports conclusion in line 17.a.

reviewed by Rob Saunders, 1/2/86 See to file 2/10/86

EPA-IX-FORM 890A

July 1885 inspirition by Long Baron Dept. of Environ - 1/18/83 mental Health reports no uncontrolled hayurens waste problem exists at this site. 2-10-86 Paul Courry e

		SOURCE	INFORMATION
19.	Observed Release		·
20.	Depth to Aquifer		
21.	Net Precipitation  Net seas. rainfall  Evaporation		
22.	Permeability of Unsaturated Zone		
23.	Physical State	·	
24.	Containment (Ground Water)	• •	
25.	Toxicity		·
26.	Persistence .		
27.	Waste Quantity		
28.	Ground Water Use		•
29.	Distance to Well		
30.	Population Served (by Ground Water)		

Name Wester	wy Electropting		Map #
	O W. Esther		Map coord.
City, Zip_L			sic
		PE DRIVE-BY ("2102")	
1. Status	a. Active ( ) Inactive	b. Different company (	( )
2. Setting	a. Urban (X) Suburban ( ) Rural ( )	b. Residential ( ) Commercial ( ) Industrial ( ) Other ( )	c. Near: RR tracks (*)  Drainage ( )  Freeway ( )  Other ( )
3. Waste	a. Group 1 ( ) Group 2 ( ) Group 3 ( )	b. Liquid ( ) Sludge ( ) Solid ( ) Other ( )	c. Undetermined ( ) None visible ( )
4. Waste Contain- ment	a. Pond () Sump () Pit () b. Piled () Scattered ()	c. Drums/Bbls ( ) Pails/Cans ( ) Dumpster ( ) Trash cans ( ) Boxes/Pallets ( ) Bags/Sacks ( ) Tanks ( ) Vehicles ( ) Other ( )	d. To: Ground ( ) ; Paving ( ) Drain ( ) Other ( )
5. Misc.	a. Odors	c. Vege	tation
	b. Topography	d. Site	observability
6. Map	A graphic site description comment on the following ials), Security, Vacan streets, landmarks, di	ption. In addition to the ing: Buildings, Paving, Sto at Areas, and Housekeeping irections, etc.	above categories, describe/ orage (other than waste mater- Don't forget to identify  Ly dirty boking  Un flowed
	(		·
	hesten E	Electropleting	& I Pec intenational
7. EVALUATIO	DN a. Possible abandon	all up for Daym, Rungled Site () Chad For ASSE	= 5 x le eal + 1 (agent) (213) ester (agent) 549-9414 of follow-up ():
	b. No problem ("211	O") ( ) d. Ref	Terral ( ) to:
:		•	Date 5-31-65
-			Name DW. & KIB
6,		(10/82]	ASAP 5-31-85

# From drive by on 5.31-85 by PW & R.B




Eastern edge of site as seen from Esther




View from Esther

15AP 5-31-85

From drive-by on 5-31-85 by P.W & R.B



View of Western portion of site



You from the corner of Esther & San Francisco

ASAP 5-31-85

River DE FOREST Los Angeles GOLDEN CHESTN LINDEN श्र D 27" MINCRYA PE AV MY GARDENIA CHERRY RAYMOND AV

2600 CI SIGNA DAWSON RAYMOND STANLEY MOL NO

> From Thomas Bros. L.A County Maps page 75

11

Department of Public Health Division of Environn	nental Health
PAGE # 1 86 2 GEFICIAL INSPECTION REPORT	NO. OF UTS.
OWNER/OCCUPANT PHONE THE TOTAL THE TOTAL THE	TIME OF DAY
15:15-21-8	/
OWNER/OCCUPANT NAME SITUS Address 820 W. ESTHO	ER
MAILING ADDRESS	TYPE OF ESTABL
(IF DIFFERENT)  During an inspection of the premises at the above address, the following violation(s) were noted y	
Licorrection within the time indicated.	CORRECTION DATE
FOLLOW-UP INSPECTION SHOWS MUCH GREEN	
COLORED STINDING WATER ACCUMULATED BE ON THE	
FLOOR THPOUGHOUT THE BLOG. AS WELL AS MULTI-	
(OLORED SLUDGE,	
THE FIRE RUN-OFF WATER 15 BEING STERED IN	
THE PUMP STATION IT THE PUBLIC SERVICE YAND.	
AT MY REGUEST KEN PHILLIPS & BOB PAI-RITCHIE	***
TOOK A SAMPLE OF THE WATER FOR ANALYSIS	·
FOR COPPER (CU) CHOMIUM (CO) ZINC (ZI) TRIVALENT	
CHROME (C. 13) AND NICYCE, THE DH OF THE WATER	
WAS MENSURED TO BE 46 USING DH STRIPS,	
SO (YNNIDE SHOULD NOT BE PRESENT.	
I THEN MET U LBED MASON SQUAD-MEMBERS.	
MILURE & JACOBSON INVESTIGATING THE ORIGIN OF	Taylor is their screening and the second of the
THE FIRE, AT THIS TIME THE INVESTIGATORS FEEL	af miles
THE FIRE WAS DELICERRATELY SET AND HAVE	
SEVERAL POSSIBLE SUSPECTS,	7
DURING-THE INVESTIGATION BY ARSON INVESTIG.	The state of the s
INCOBSON WAS EXPOSED TO THE ACCUMULATED	
LIQUID IN THE DIKED AREA AROUND THE	A STATE OF THE STA
PLATING BATHS WHICH BEGAN BURNING HIS HAND.	
THE AH OF THE MATERIAL AS SHOWN BY AH INDICAT	
SIGNING FOR RECEIPT OF THE ABOVE NOTICE IS NOT AN ADMISSION OF THE FACTS OF THE VIOLATION (S)	SET FORTH THEREIN
K.L.	lele
Received By Represe	nionve
Type of Visit Violations Correction Referral	and the second s
REFERENCE LA PL CON TO Service	mit/EIR/Variance/License
Inspection AG/R	DC/F
Areas (Follow-up) Animal Brain Complaint Samples Other Samples/Type Abated Order	VB/G

FORM HL-594 3/

FORM HL -512 B/67

DISTRICT SANITARIAN